# Tubing Conveyed Perforating (TCP)

Presenter: Ahmed N. Al Fahdi

Supervisor: Eng. Ali Al Busaidi

## Agenda

- TCP Overview
- HSE Considerations
- TCP
  - Guns & Charges
  - Firing Heads
  - Packers
  - BPV
  - RA Marker
- Case Study 1: Oriented Perforation
- Case Study 2: Water production perforation
  - Calculations (Underbalance, TCP-Correlation)

## HSE considerations (1/2)

- 9 Life Saving Rules
- IHTIMAM
- Musta'ed



#### **Musta'ed Worksite Activity Preparation Checklist**

RAY-OG-FRM-230 (1.0)

Activity Date:	28-Sep-24	Unit (Rig/Hoist)	Rig-81
Planned Activity:	Perforation	Job Leader Name & Signature	IDRIS ALMAYHAI

No.	7 Pillars of - Musta'ed		Check box ( ✓ ) Tick mark Ensure Applicable points	Remarks (if any)
		Ø	available & validated	
1	Plan		Procedure Work Instruction Risk Assessment Lift Plan PTW (Permit to Work) Third Party Checklist Well Control Barriers identified Role Verifiy Understanding	
2	Check Equipment		Certification COC* & COS* Calibrated / Inspected Tests/Fit for purpose Back-up readily available	
3	Prepare Area		Housekeeping Zone Management (Red Zone,No-Go) SIMOPS/Above,Below,Beside Emergency Preparedness	
4	Control Energy		Isolate(Lock-out,Tag-out,Test) Line of Fire (Manage Stored Energy, Pressurized Equipment,Tension Lines, etc	
5	Communicate		Toolbox TalK TRIC (Transition to work – Ask open questions) Hand Signals Signage Learning From Incidents (LFI) Focus Area -Pers⊡al and Well Process safety	
6	Final Checks	Checks 2 100% ready to go Complete PTW Emergency Response/Plan in Place Walk the Line with P&ID		
7	Start Work		Comply-Intervene-Respect (Golden Rules) Adhere to Life Savig Rules Well Barriers/ DROPS/Hands Off STOP re-assess risk if any changes	

Note: COC\* & COS\* (Certificate of Compliance & Certificate of Service)

Starting the job is **not** the first step

## **HSE Considerations**

- When Storing in Magazine:
- Magazines must be located in the most isolated place available.
- They must be well ventilated, dry, reasonably cool, substantially constructed (Bullet and missile proof if needed), securely looked, weather resistant, fire resistant, theft resistant.
- Don't store in wet or damped areas or near excessive heat or flame sources.
- Don't store explosives with detonators in the same box, containers or magazines.
- 5. Don't store any sparking material.
- 6. Don't allow vegetation to grow within 25 feet of magazines.

#### SynaEnergetics

#### DO's and DON'TS

Instruction and Warning

ormation applicable to Oil Well Perforating Operations extracted from "Do's and Don'ts Instructions and Warnings" adopted by the Institute of Makers of explosives. Read this in all cases before using any explosives product.

If after reading this pamphlet, you have any questions or doubts as to how to use these explosives products - DO NOT USE THEM. Consult the manufacturer for additional information.

It is the responsibility of all persons who use explosives to know and follow all approved safety procedures and to comply with all applicable Federal, State and Local laws, regulations and ordinances.

LOCK UP EXPLOSIVES. KEEP FROM CHILDREN.

AVOID FLAME, HEAT, SPARK AND IMPACT.

The explosives in this package were manufactured and packed under careful supervision and inspection. However, the contents may become damaged by improper handling or storage beyond the control of the manufacturer; therefore, they should be carefully inspected before using.

#### PREVENTION OF ACCIDENTS IN THE USE OF EXPLOSIVE MATERIALS

The prevention of accidents in the use of explosive materials is a result of careful planning and observance of the best known practices. The user must remember that he is dealing with a powerful force and that various devices and methods have been developed to assist him in directing this force. He should realize that this force, if misdirected, may either kill or injure both him and his fellow workers.

All explosive materials are dangerous and must be handled and used with care either by or under the direction of competent, experienced persons. All commercial explosive materials are designed to detonate when supplied with a sufficient amount of initiating energy. Unfortunately, the explosive material cannot differentiate between initiating energy purposely supplied and that accidentally supplied. It is the responsibility of all persons who handle explosive materials to know and to follow all approved safety procedures. This responsibility includes the necessity of being familiar with, and observing, federal, state,

It is obviously impossible to include warnings or approved methods for every conceivable situation. A list of suggestions to aid in avoiding the more common cases of accidents is set forth herein. Additional information pertaining to explosive materials is available in the Institute of Makers of Explosives Safety Library Publications listed below. Copies of these publications may be obtained by writing the Institute of Makers of Explosives. 420 Lexington Avenue, New York, New York 10017, or from your explosive materials supplier. Standard Storage Magazines (No. 1); American Table of Distances (No. 2); Suggested Code of Regulations for the Manufacture, Transportation, Storage, Sale, Possession and Use of Explosive Materials (No. 3): Recommended Industry Safety Standards (No. 6); Agricultural Blasting (No. 11); Safety in the Transportation, Storage, Handling and Use of Explosive Materials (No. 17); Safety Guide for the Prevention of Radio Frequency Radiation Hazards in the Use of Electric Blasting Caps (No. 20); IME Standard for the Safe Transportation of Electric Blasting Caps in the

If, after carefully reading the entire leaflet, you have any questions or doubts as to how to use these products – DO NOT USE THEM – consult the manufacturer for additional information

#### "DO'S AND DON'TS" INSTRUCTIONS AND WARNINGS - GENERAL


- DO obey all laws and regulations applicable to explosive materials.
- DON'T abandon any explosive materials.
- DON'T allow any source of fire or flame within 100 feet of a blast area (except for lighting safety fuze) or within 50 feet of a magazine or vehicle containing explosive materials.
- DON'T expose explosive materials to flame, excessive heat, sparks or impact.
- DON'T fight fires in explosive materials. Remove all personnel to a safe location immediately and guard the area against intruders.
- DON'T shoot into explosive materials, magazines, or vehicles loaded with explosive materials. DON'T allow unauthorized persons near explosive materials.

#### WHEN TRANSPORTING EXPLOSIVE MATERIALS

- DO see that any vehicle used to transport explosive materials is in good mechanical condition and properly designed, equipped, and placarded for
- DON'T drive or park vehicles containing explosive materials in congested areas unless it cannot be avoided. DON'T transport flammable or corrosive substances with explosive materials.
- DO load and unload explosive materials carefully.
- DO see that other explosive materials are separated from all types of detonators where a separated to transport them in the same vehicle

## What is TCP?

- A perforation carried out by means of tubing instead of wireline.
- Perforation is needed to make conductive path for fluids from virgin reservoir rock to wellbore.





## Why use TCP over Wireline?

- 1. For large guns, large intervals, multi-intervals, multi-zone.
  - TCP allows for the simultaneous perforation of long or widely spaced intervals in a single trip, which can significantly reduce rig time compared to multiple wireline runs.
- 2. For wells with high deviation angle
  - Horizontal wells
  - Wireline high key-seating risk in J-shaped tangent wells or S-shaped wells
- 3. Reduced Risk of Wellbore Damage
  - The ability to perform operations underbalanced which helps protect the integrity of the wellbore during perforation.
  - Underbalance perforation provides clean tunnels.
- Other Advantages of TCP
  - Extreme Overbalance perforation (Mini frac).
  - Ability to inject acid in the same run.
  - Double and Triple Casing Perforation.

## Charges (1/4)

- Components
  - 1. Case made of Zinc or Steel
  - 2. Conical Liner
  - 3. Main explosive made of secondary high explosive
  - 4. Detonating Cord made of secondary high explosive







## Charges (2/4)

- Types:
  - 1. DP
  - 2. GH
  - 3. BH
  - 4. DynaSlot (Cement Squeeze & Abandonment Wells)

#### **Configuration Schematic**



#### **Shot Pattern**



## Charges (3/4)

- Deep Penetrating (DP)
- Good Hole (GH)
- Big Hole (BH)

DynaSlot

DynaSiat Shell Presenation




## Charges (4/4)

Types of explosive:

Table 1. Relative Energies of Explosives

Туре	Scale	Comments	
RDX	100	none	Blue Det. Cord
HMX	105	none	Yellow Det. Cord for high Temp.
HNS	70	none	
PYX	65	PYX detonating cord is not recommended for TCP as it creates a lot of interference between charges.	

- 1. Primary Lead Azide  $Pb(N_3)_2$ : Detonators & Boosters C-63
- 2. Secondary **RDX/HMX/HNS**: Det. Cords, charges



## Guns

Shoot & Pull Hollow Carrier Gun Systems



**Link Gun Systems** 



**Strip Gun Systems** 



Shoot & Drop
Fragmenting Gun Systems



## Firing Head

- Contains the primary initiator explosive
- Types:
  - 1. Mechanical Drop Bar FH
  - 2. Hydraulic
  - 3. Auto-vent

## Cont. FH (1/3): Mechanical FH

 Dropped from the surface to initial the mechanical actuation type firing head in well within "40 Deg" deviation. It has brass indent can be used to determine if the drop bar reached firing head.

#### Limitations:

- 1. Cannot be used for high deviation wells; there is a risk of it getting stuck.
- 2. Unlike other methods, the debris can cause some issues that require fishing.

#### **Desilting Mechanical Firing Head**

The Desilting Mechanical Firing Head is a kind of debris proof firing head is designed to fire guns in TCP. Drop bar must be required. The firing head used in light mud well and little deviated well

#### Feature

- 1, Sample, Reliable, Easy to us
- 2. Desilting

	Structure	Part Name	Qty
Item	P. N.		1
1	RADMF01093001	Upper Sub	1
2	RADMF01093002	Pup joint	1
3	RADMF01093100	Mechanical Firing assembly	
4	RADMF01093004	Detonator house	1
-		Centralizer tube	2
5	RADMF01093005	Stop tube	2
6	RASTX01268001	120	2
7	GB/T 95 6	Washer	4
8	AS-115	0-ring φ 17. 12×2. 62	
9	RADMF01093003	Centralizer disk	1
10	ANSI B18. 3	Set Screw 5/16-24 UNF x 0. 75	3
11	RADMF01093006	Guide rod	1
12	RGCMX01288001	Coupling	1
13	RADMF02093001	lower stacking adapter	. 1
14	AS-224	0-ring φ 44. 04×3. 53	2
15	RADMF02093002	Lower sub	1

#### Technical Parameters

Part Number  0.D. (mm)  Total Length (mm)		RADMF02093000 93	
		Connection	Upper Thread
Connection	Bottom Thread	2 3/4-6ACME BOX	
Temperature Rating (°C)		200°C	
Pressure Rating (MPa)		70MPa	
Type of Detonator		DYNA	


## Cont. FH (1/3): Mechanical FH: Drop Bar

#### • Dimensions:

- Fishing neck (O.D) = 20.3mm or 0.800"
- Length = 1830 mm or 6.0 ft
- Weight = 8.9 kg
- Dimensions = 1830mm x 28.57mm

#### Recommendations

- 1. Change brass indicator after each run
- 2. Don't use for more than 40 Deg deviation. [As per Dyna manual]



## Cont. FH (1/3): Mechanical FH: Drop Bar


- Has brass tag to show the impact with firing head.
- The dimensions of DB are import for fishing.





## Cont. FH (2/3): Auto-vent FH

- Activated using absolute pressure.
  - Absolute pressure = Hydrostatic pressure + Applied pressure (pumps)
  - ±5%
- Commonly used for multi-zone/ multi-interval perforation along with Mechanical FH and time delay fuses.
- Commonly used for high deviation wells
- Works better with debris, as the applied pressure can be beneficial for cleaning up the debris via direct and/or reverse circulation.
- Shear pin/ shear stud is calculated by engineer depending on required pressure, the pumps available at the Rig/Hoist



## Cont. FH (3/3): Hydraulic

- Same working principle as Auto-vent FH
- It requires ported sub (flow Sub) for circulation.
- Required pressure depends on:
  - 1. Temperature
  - 2. Mud weight
  - 3. True Vertical Depth (TVD)

## Packers: Overview [As Per RAY-OG-PKR (3.0)]

#### • What?

 Retrievable Map/Anton/RTTS/CREST III Packers: are types of downhole isolation tools which will be unset and retrieved from the wellbore after use.


#### • Why?

 Used to isolate the annulus from the production tubing, allowing a controlled production, injection or treatment, incorporating a mean of securing the Packer against the casing or liner wall, such as a slips arrangement, and a means of creating a reliable hydraulic seal to isolate the annulus, typically by means of an expandable elastomeric element.

## Packers: Example of CREST III



## Packers: Map Schematics



## Packers: Setting-up The Map Packer

- 1. Pick up on tubing (String in tension position)
- 2. Rotate ¼ **turn** to the RIGHT slack off on the tubing, set down weight on packer. This sets the slips, closes the bypass & compresses the packing elements.


$5000~\mathrm{lbs}  o \mathrm{kg}$	2267.962 kg
# Weight Per 1"	
$Weight := 2000 \ \mathrm{lbs}$	2000 lbs
# Weight Per 7"	
$Weight\cdot 7 o \mathrm{kg}$	$6350.293~\mathrm{kg}$

## Packers: Unsetting The Map Packer

- 1. Make sure all pressure is bled off from the annulus before unsetting Packer
- 2. Pick up to strings full up weight slowly. This will open packer bypass, and pressure will equalize across annulus and tubing. Then continue pickup and go for packer release. Packer should take around 5k lbs 10k lbs weight extra while un-setting.
- 3. Once Packer has been unset, lower string 10 ft to ensure it is in safety position.
- 4. Continue operations as usual.

## Packers: Corrosion & Counter-measures

• Pitting Corrosion is localized form of corrosion by which cavities or "holes" are produced in the material, most cases of pitting are believed to be caused by local cathodic sites in an otherwise normal surface. Apart from the localized loss of thickness, corrosion pits can also be harmful by acting as stress risers.





## **BPV** (Bar Pressure Vent)

#### • Why?

 The BPV helps to control and vent excess pressure that may build up in the wellbore during perforation. This is essential for maintaining the desired underbalance condition, which is crucial for effective perforation and minimizing formation damage.

#### • How?

- 1. It is operated by dropping a bar to break the impact pin;
- 2. when the pins broken, tubing pressure forces the sleeve upward against the air chamber to open the production vents.
- 3. The piston is held up in its place by a snap ring allowing the fluid circulation.

## Cont.

#### Other remarks


- The BPV may be opened prior to firing the guns to achieve a packer test or it may be opened simultaneously with the guns firing to achieve a differential in wells with existing perforations.
- The DBPV is opened by 500 psi or more pressure in the tubing, applied or hydrostatic. The sliding sleeve is isolated from the tubing pressure by a break plug.
- To break the impact pin, the minimum tool OD (Drop Bar or another tool) is 1.25 in.
- NOTE: 500 psi minimum actuating pressure must be tubing pressure, not differential pressure, do not confuse the two.

 $500 \text{ psi} \rightarrow \text{kPa}$   $1.25 \text{ inch} \rightarrow \text{mm}$  31.75 mm

## Cont. BPV

- Parts (LTR):
  - 1. Shear Sleeve
  - 2. Bottom Sub
  - 3. Upper Sub







	Part Name	P. N.	2	
Item	RCDBV01288000	RCDBV01288000	Qty	
1	Upper Sub	RCDBV01288001	1	
2	0-ring φ 66. 27×3. 53	AS-231	3	
3	Sliding sleeve	RCDBV01288002	1	
4	0-ring φ 75. 79×3. 53	AS-234	1	
5	Impact Pin	RCDBV01288003	1	
6	0-ring φ 6.07×1.78	AS-010	2	
7	0-ring φ 75.87×2.62	AS-151	2	
8	Grip Ring	RCDBV01288004	1	
9	Set Screw 1/4- 20UNCx0.25	ANST B18. 3 1/4-20UNCx0. 25	2	
10	Bottom Sub	RCDBV01288005	1	
11	Shear sleeve	RCDBV01288006	1	
12	Shear pin	RAPFH01080107	4	

### Cont. BPV Location

- The Drop bar Pressure Vent Sub is normally run between the firing head and the packer in a TCP string.
- If a gun drop sub is used, the Drop Bar Pressure Vent Sub is normally run below the gun drop sub.
- It is recommended that the Drop Bar Pressure Vent Sub be placed at least 30 ft above the firing head and at least 30 ft below the gun drop sub or packer.
- This spacing allows the drop bar to regain momentum after breaking the impact pin.

## Radioactive Marker (MA Marker)

- Used to determine accurately the exact location of TCP string, and how much adjustment is needed to reach the target depth.
- Uses Cobalt isotope 60
- Wireline/Slikline lowers GR CCL/ Memory GR CCL tool to locate the "Pip Tag".
- Sizes:
  - $2^{7}/_{8}$
  - $2^{1}/_{2}$





# Case Studies: Oriented Perforation


MM-1382



## Overview

- Objective:
  - The job aims to do a perforation in a well where a Fiber Optics Cable exists. It's used to gather live data about well.
- Well No. & Rig/Hoist No.:
  - MM-1382
  - HFBU-04
- Date:
  - 10/Aug/2024
- Outcome:
  - Failure

## Technical Details: Header



New Well

Measured Above Hole, Below Drill Floor [Meters]


856.5-879.9 (23.4 m), 888.2-919.2 (31 m), 922.2-953.1 (30.9 m) Mahbdf

4.50" HSD, 12 SPF, 22.7g DP RDX (Loaded @ 8 SPF)

TCP Over Balance (Shoot & Pull) String Diagram with UBHO & Gyro for Gun Orientation


Since it's overbalance, the Packer is used only as a centralizer (Universal Bottom Hole Orientation Sub)
Real North as Ref.

## Technical Details: Proposed String Diagram



16 Guns

## Technical Details: Footer




Using Wireline/Slickline










## Verification





## What went wrong?

- Unsuitable screw size.
- Longer screw, which is designed for 5" tandem subs, used instead shorter screw.



## **Another Oriented Perforation failure**

Misfire resulted in partial detonation of charges due to missing O-rings in the adjustable tandem subs. Visual check of subs will not show the problem unless you open the tandem subs.





# Case Study 2: Well Water Production Perforation

MARMUL NW-50



## Overview

- Objective:
  - Perforating water production well.
- Well No. & Rig/Hoist No.:
  - MARMUL NW-50
  - Rig-81
- Date:
  - 19-Oct-2024
- Outcome:
  - Success


## Technical Details: Header

	Document Number: RAY-OF-FRM-1402 (2.0)									
		Client	PDO	Job Reference TCP-24-0		9-40	Date	19-Oct-24		
		Field	MARMUL	Total Depth (Mahbdf)	9.5/8", 40#, K-55 7", 29#, K-40		Run No.  Top (Mahbdf)  Surface	1 Bottom (Mahbdf) n/a		
		Well	MARMUL NW-50	Hold Up Depth (Mahbdf)						
		Rig	Rig-81	Casing Details						
	AY	Formation Zones Mud Weight (kPa/m)		HSAK1			Liner Details	Surface	1011.00	
INTE	RNATIONAL GAS			10.1 WSW			Annulus Hydrostatic at Pa	BHT (Deg C)	55° Deg C	
OIL 8	GGAS	Cushion Weight (kPa/m)	10.1 WSW	Cushion Hydrostatic at Firing Head (kPa) 8000			U.B Pressure (kPa)	2000		
Unit	TCP	Max. Deviation (°)	0 ° Deg	Max 1.48 ° Deg	Formation Pressure at To	p Zone (kPa)	10000	Existing Perfs (Y/N)	No	
0	0 Gun Type:									
	874-902.3 (28.3) , 907.2-1007 (99.8) Mahbdf					4.50" HSD,22.7 g, 12 SPF, DP RDX				
	Final - TCP Under Balance (Shoot & Pull) String Diagram									

## Technical Details: Proposed String Diagram

Tool String	Description	Responsible Company	O.D.(")	I.D.(")	Вох.	Pin.	Length. (m)	Top Depth. (m Mahbdf	) Bottom Depth(m)Mahbdf
<b>9</b>	Circulation Head	PDO	11.000	0.000	0	0	0.00	-2.80	-2.30
	joints 3 1/2" EUE (9.3# ) TBG to surface	PDO	3.500	2.990	3.5" EUE	3.5" EUE	817.84	-2.30	815.54
	3 1/2" EUE RA Marker PIP TAG AT SN (25) 815.74 M	RAY	3.500	2.990	3.5" EUE	3.5" EUE	0.34	815.54	815.88
	2 ea 3 1/2" EUE TBG Joints	PDO	3.500	2.990	3.5" EUE	3.5" EUE	18.67	815.88	834.55
	3 1/2" EUE PUP Joint.	RAY	3.500	2.990	3.5" EUE	3.5" EUE	1.48	834.55	836.03
	7" Mechanical Retrievable Packer SN (11)	RAY	5.970	2.250	3.5" EUE	3.5" EUE	2.97	836.03	839.00
	1 ea 2 7/8" EUE TBG Joints	PDO	3.670	2.440	2.875" EUE	2.875" EUE	9.42	839.00	848.42
	2 7/8" EUE BPV (Bar-drop Production Valve) SN (23)	RAY	3.670	2.440	2.875" EUE	2.875" EUE	0.43	848.42	848.85
	2 ea 2 7/8" EUE TBG Joints	PDO	3.670	2.440	2.875" EUE	2.875" EUE	19.02	848.85	867.87
	Drop Bar Firing Head (2-7/8") with Pup joint	RAY	3.670	****	1.57" No-Go	2.875"EUE	1.70	867.87	869.57
	4.5" Safety Spacer	RAY	4.500	****	2.375" 6 TPI	2.375" 6 TPI	4.43	869.57	874.00
	4.50" HSD, DP, RDX, 12 SPF	RAY	4.500	****	2.375" 6 TPI	2.375" 6 TPI	28.30	874.00	902.30
	4.5" Blank Spacer	RAY	4.500	****	2.375" 6 TPI	2.375" 6 TPI	4.90	902.30	907.20
	4.50" HSD, DP, RDX, 12 SPF	RAY	4.500	****	2.375" 6 TPI	2.375" 6 TPI	99.80	907.20	1007.00
<b>1</b>	Bottom Plug	RAY	4.500	****	****	2.375" 6 TPI	0.27	1007.00	1007.27


## Technical Details: Footer



## Underbalance Calculations (1/2)

# Given Info	
FormationPressure := 10000  kPa	10 MPa
$Required Underbalance := 2000~\mathrm{kPa}$	2 MPa
# Calculation	
$Required Tubing Hydrostatic := Formation Pressure - Required Underbalance \rightarrow \mathrm{kPa}$	8000  kPa
$TubingCushion := rac{10.1  ext{ kPa}}{ ext{m}}$	$\frac{10.1 \text{ kPa}}{\text{m}}$
$Filled_{tubing} := rac{RequiredTubingHydrostatic}{TubingCushion}$	$792.079 \mathrm{\ m}$


## Underbalance Calculations (2/2)



RAY-OG-FRM-1428 (2.0)


## Gun Loading Sheet (1/2)

#### 18-Full Loaded Guns




## Gun Loading Sheet (2/2)

#### 3-Partial Loaded Guns & One Safety spacer



## **Depth Correlation**



Go up by 1.5m

## Verification

- Using specialized device to confirm there has been firing.
- It uses acoustic receivers to confirm firing; however, it can't tell you if the firing is full or partial.



# Job Log

			JOE	3 LOG
Client:	PDO		SAP P.O.Number:	
Well Name / Field	MARMUL NW	-50	Job Number:	TCP-24-09-40
Well Location:	MARMUL		Date:	28-Sep-24
Rig:	Rig-81		Job Discription:	TCP Shoot & Pull Underbalance
Date	Time			Event
28-Sep-24	16:00	TCP (	Crew and Guns arrived to the w	vellsite.
29-Sep-24	6:00	PJSN	I held in the rig floor priorr pick	ing up the guns.
	6:10	Start	Picking up & RIH 4 1/2" HSD	12 SPF guns.
	9:45	Make	e up 2 7/8" EUE Drop Bar-Mech	nanical Firing Head.
	9:50	Pick	up and RIH 2 joint of 2 7/8" EL	JE Tubing, and fill up with 10.1 KPA/M water.
	9:55	Make	e up 2 7/8" EUE Drop Bar Pres	sure Vent (BPV_Circulating).
	10:00	Pick	up and RIH 1 joints of 2 7/8" E	UE tubing and fill up with 10.1 KPA/M water.
	10:15	Pick	up & RIH Packer assembly (7"	Retreivable Packer, & 3 1/2" EUE Pup-Joint).
	10:25	Pick	up and RIH 2 joints of 3 1/2" E	UE, tubing and fill up with 10.1 KPA/M water.
	10:30	Make	e up 3 1/2" EUE RA-Marker.	
	10:45	Start	Picking up & RIH 3 1/2" EUE t	ubing.
	14:00	Com	oleted RIH initial stick up 0.80	m.
	14:30	Rig u	p RAY wire line to correlate RA	Marker Depth.
	14:45	RAY	wire line Start RIH.	
	15:30	RAY	wire line correlated RA-Marker	Depth at 817.24 M.deeper 1.5 M, it should be at (815.74M).
	16:00	PDO	office approved the correlation	on result & RAY wire line Start POOH.
	16:15	RAY	Wire line Rig Down.	
	16:30	make	e up safety vale & Final Stick u	p 2.3 m.
	16:35	Set P	acker, and apply 8 ton slack o	ff (String weight 35 ton).
	16:45	Close	BOP and apply 5000 KPA to t	est Packer Integrity.
	17:00	PJSN	Held before Drop the bar to fi	re the gun.

Client Representative:	SAID	RAY Representative: IDRIS ALMAYHAI
30-Sep-24	2.45	TCP Crew and Equipment left the wellsite.
	2:15	POOH Guns completed & confrimed all Guns Fired.
	10:55	Disconnected and lay down Drop Bar-Mechanical Firing Head.
	10:35	POOH and lay down 2 joints of 2 7/8" EUE tubing & remove the detonating bar.
	10:25	Disconnected & Lay down 2 7/8" Bar Pressure Vent (BPV_Circulating tool).
	10:15	POOH and lay down 1 joints of 2 7/8" EUE tubing.
	10:10	Disconnect & Lay down Packer assembly, (7" Retreivable Packer & 3 1/2" EUE pup-joint).
	10:00	POOH & lay down 2 joint of 3 1/2" EUE tubing.
30-Sep-24	9:40	Disconnect & Lay Down 3 1/2" EUE RA-Marker.
	19:45	Start POOH & lay down .
	17:45	Flow check for 15 min, losses recorded.
	17:30	Revers out oil & Gas observed at surface.
	17:15	Bleed off casing and pick up TCP String to unset the Packer.
	17:05	Drop the detonating bar, and within 1.5 min, strong shock obseved in the string.

# Backup Slides


#### Misfire Procedure Guns Misfired or thermally Overexposed Conduct a safety meeting and review safety procedures Record t0 (time of the last attempt to fire or start POOH) and POOH up to 61m (200ft) below wellhead/sea floor. NO Wait at 61m (200ft) until 30min have Have 30min elapsed from t0 elapsed from t0? YES Continue POOH to Surface Used the IR thermometer or perform "water Test" Water Bubble or boil off, Leave gun where it is! Clear the area and or IR thermometer Read wait 2hrs. >100degC (212F) NO Measure the temperature with an IR thermometer. record the temp T1 and time Clear the area and wait for 15min (i.e.t2-t1). Take another temperature, and record the T2 and time YES T2>T1? NO Proceed with disarming/disassembly procedure


## Packers: Map: Setting-up the Packer

- Mark string at Gun on Depth (GOD) position. Measures 0.35m from GOD to below of the string and put 2nd mark.
- RIH string to maximum distance at rig floor and pick up string back to the 2nd mark.
- Rotate string to the RIGHT turn (clockwise) approx. 1 turn per 1000m depth. Hold the torque and wait for 1 minute (to allow the torque to be transmitted to the bottom).
- Lower string until down weight starts to decrease. When packer starts to set, release the torque and continue to slack off required weight onto tool as per reference technical manual for each packer size approx. 2000 lbs per 1" packer sizes.
- Close BOP and perform casing pressure test. Note: if any leak observed, increasing weight on packer **5 klbs** and repeat pressure test. If leak is still observed change the setting depth and repeat pressure test.

## Techniques of perforation

### **Underbalance TCP String using Drop Bar Firing Head: RA Marker** 3.1/2 EUE tubing 7" PKR X-over 2.7/8 EUE tubing **BPV** 2.7/8 EUE **Drop Bar Firing Head** Guns






## Acid wash or Stimulation with TCP string

#### **Acid wash or Stimulation with TCP string**

- In a single run and after firing the guns, TCP string is moved down placing the circulating valve across the perforation zone. Tubing volume is displaced with Acid and packer is set then acid pumping activity into the perforated zone is obtained.
- The technique should consider HSE mitigation of acid handling and suitable packers and/or other tools for acid handling is required (Nickel Coated).

#### **Benefits:**


- Save rig time/cost
- Enhance production as result of acid cleanout



## Multi-zone Perforation

#### **Multi-zone Perforation**


- 1. Several TCP runs to achieve desired SUB pressures utilizing one mechanical firing head on each run.
- One TCP run utilizing long gun spacers in between the zones;SUB is also achieved.
- 3. One TCP run utilizing one mechanical and one/two absolute pressure firing head; SUB is achieved for only the top zone.



## ROPS-Gyro

#### **Ray Oriented Perforation System (ROPS):**

- Eliminating extra runs with ability to increase shot density with improved detection accuracy of +/- 7.5 degrees. (36 samples per revolution.)
- Ability to detected FOC with well deviations < 5 degrees by implementing Gyro in the string while perforation.
- Process verifies the actual relative bearing or magnetic north offset corresponds to exact value required.
- Ability to provide FOC position while RIH at given depths (36 samples per revolution in about one minute).






## **UBHO Sub**



## **CCL Correlation Log**



## Ready Box



# Casing Sizes

Casing Size (OD in)	Coupling Size (OD in)	Common Bit Sizes (in)
4 1/2	5.0	6, 6 1/8, 6 1/4
5	5.563	6 1/2, 6 3/4
5 1/2	6.05	7 7/8, 8 3/8
6 5/8	7.39	7 7/8, 8 3/8, 8 1/2
7	7.656	8 5/8, 8 3/4, 9 1/2
8 5/8	9.625	11, 12 1/4
9 5/8	11.75	12 1/4
10 3/4	11.75	15
13 3/8	14.375	17 1/2, 17
18 5/8	19.625	22
20	21.0	24,26
24	25.25 &, 25.5	28